

WK 36

36

DART AEROSPACE LTD	Work Order:	18159
Description: Ski Installation Kit	Part Number:	K10016
	Qty:	1

Step	Location	Procedure	By	Date	Qty																																																				
1	DC	Open Traveller	KJ	02.09.03	1																																																				
2	DC	Photocopy bluefiles: K10016 and create labels per PPP K10016 NK 36 KJ																																																							
3	PK	Pick: <table><thead><tr><th>Qty</th><th>Part Number</th><th>Description</th><th>Batch</th></tr></thead><tbody><tr><td>18</td><td>D2182B050</td><td>Rubber cushion</td><td>_____</td></tr><tr><td>36</td><td>D2274</td><td>Radius block</td><td>_____</td></tr><tr><td>18</td><td>D2438</td><td>Clamp</td><td>_____</td></tr><tr><td>16</td><td>D2529</td><td>Washer</td><td>_____</td></tr><tr><td>2</td><td>D3003-1</td><td>Ski fwd section</td><td>_____</td></tr><tr><td>2</td><td>D3004-1</td><td>Ski center section</td><td>_____</td></tr><tr><td>2</td><td>D3005-041</td><td>Wearplate</td><td>_____</td></tr><tr><td>2</td><td>D3006-041</td><td>Wearplate</td><td>_____</td></tr><tr><td>36</td><td>AN4-15A</td><td>Bolt</td><td>_____</td></tr><tr><td>36</td><td>AN960JD416</td><td>Washer</td><td>_____</td></tr><tr><td>36</td><td>MS21042L4</td><td>Nut</td><td>_____</td></tr><tr><td>1</td><td colspan="3">paper work package from step 2</td></tr></tbody></table>	Qty	Part Number	Description	Batch	18	D2182B050	Rubber cushion	_____	36	D2274	Radius block	_____	18	D2438	Clamp	_____	16	D2529	Washer	_____	2	D3003-1	Ski fwd section	_____	2	D3004-1	Ski center section	_____	2	D3005-041	Wearplate	_____	2	D3006-041	Wearplate	_____	36	AN4-15A	Bolt	_____	36	AN960JD416	Washer	_____	36	MS21042L4	Nut	_____	1	paper work package from step 2					
Qty	Part Number	Description	Batch																																																						
18	D2182B050	Rubber cushion	_____																																																						
36	D2274	Radius block	_____																																																						
18	D2438	Clamp	_____																																																						
16	D2529	Washer	_____																																																						
2	D3003-1	Ski fwd section	_____																																																						
2	D3004-1	Ski center section	_____																																																						
2	D3005-041	Wearplate	_____																																																						
2	D3006-041	Wearplate	_____																																																						
36	AN4-15A	Bolt	_____																																																						
36	AN960JD416	Washer	_____																																																						
36	MS21042L4	Nut	_____																																																						
1	paper work package from step 2																																																								
4	QC4	Inspect 100% Kit for completeness																																																							
5	KP	Identify and pack as per PPP K10016																																																							
6	AC	Cost / part																																																							
7	DC	Close W/O Inspect Level 21																																																							

Rev	Date	Change	Revised By	Approved
A	02.08.23	New issue	KJ	KJ

REFERENCE ONLY

 RELEASED
 02/08/27 RF

OK 36

DAVT AERC SPACE LTD	Work Order:	18159
Description: Ski Installation Kit	Part Number:	K10016
	Qty:	1

Step	Location	Procedure	By	Date	Qty																																																				
1	DC	Open Traveller	JA	02.09.06	1																																																				
2	DC	Photocopy bluefiles: K10016 and create labels per PPP K10016 WK 36 JA	JA	02.09.08	1																																																				
3	PK	Pick: <table><thead><tr><th>Qty</th><th>Part Number</th><th>Description</th><th>Batch</th></tr></thead><tbody><tr><td>18</td><td>D2182B050</td><td>Rubber cushion</td><td>B18020-B17095</td></tr><tr><td>36</td><td>D2274</td><td>Radius block</td><td>B17929</td></tr><tr><td>18</td><td>D2438</td><td>Clamp</td><td>B17512</td></tr><tr><td>16</td><td>D2529</td><td>Washer</td><td>B17520</td></tr><tr><td>2</td><td>D3003-1</td><td>Ski fwd section</td><td>B18119</td></tr><tr><td>2</td><td>D3004-1</td><td>Ski center section</td><td>B18120</td></tr><tr><td>2</td><td>D3005-041</td><td>Wearplate</td><td>B141314</td></tr><tr><td>2</td><td>D3006-041</td><td>Wearplate</td><td>B141309</td></tr><tr><td>36</td><td>AN4-15A</td><td>Bolt</td><td>M10931</td></tr><tr><td>36</td><td>AN960JD416</td><td>Washer</td><td>M11151</td></tr><tr><td>36</td><td>MS21042L4</td><td>Nut</td><td>M10132</td></tr><tr><td>1</td><td colspan="3">paper work package from step 2</td></tr></tbody></table>	Qty	Part Number	Description	Batch	18	D2182B050	Rubber cushion	B18020-B17095	36	D2274	Radius block	B17929	18	D2438	Clamp	B17512	16	D2529	Washer	B17520	2	D3003-1	Ski fwd section	B18119	2	D3004-1	Ski center section	B18120	2	D3005-041	Wearplate	B141314	2	D3006-041	Wearplate	B141309	36	AN4-15A	Bolt	M10931	36	AN960JD416	Washer	M11151	36	MS21042L4	Nut	M10132	1	paper work package from step 2			Q	02.09.10	1
Qty	Part Number	Description	Batch																																																						
18	D2182B050	Rubber cushion	B18020-B17095																																																						
36	D2274	Radius block	B17929																																																						
18	D2438	Clamp	B17512																																																						
16	D2529	Washer	B17520																																																						
2	D3003-1	Ski fwd section	B18119																																																						
2	D3004-1	Ski center section	B18120																																																						
2	D3005-041	Wearplate	B141314																																																						
2	D3006-041	Wearplate	B141309																																																						
36	AN4-15A	Bolt	M10931																																																						
36	AN960JD416	Washer	M11151																																																						
36	MS21042L4	Nut	M10132																																																						
1	paper work package from step 2																																																								
4	QC4	Inspect 100% Kit for completeness	R	02.09.10	1																																																				
5	KP	Identify and pack as per PPP K10016	Q	02-09-10	1																																																				
6	AC	Cost part 669.87	JA	02.09.11	1																																																				
7	DC	Close W/O Inspect Level 21	JA	02.09.11	-																																																				

as per attached

5372
5772
4635

BB 800 02-09-11

Rev	Date	Change	Revised By	Approved
A	02.08.23	New issue	KJ	

RELEASED
02/08/27 RF

Dart Aerospace Ltd

Work Order:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector

NCR		WORK ORDER NON-CONFORMANCE						
DATE	STEP	Description of NC section A	Corrective Action Section B		Sign & Date	Verification Section C	Approval Design Mgr	Approval QC Inspector
			Initial					

PAR#: _____ Fault Category: _____ DQA: _____ Date: _____

NOTE: Date & initial all entries
H:\Admin-QA\ISO\forms\w\oncB.doc

QA: N/C Closed: _____ Date: _____

A.B.I.

Job Costing Report

Dart Aerospace Ltd.
Hawkesbury

Aug 30, 2002
02:19 pm

Work Order No : 0018159
Project Name : *K10016
Project For : wk 36
Work Order Type : Main
Main WO Number :
House Part Number : *K10016
Description : Ski Installation Kit
Manufactured : Yes
Amount Req'd : 1
Amount Done : 0
Start Date :
Est Finish Date : 09-06-02
Act Finish Date :
Drawings Req'd : No
Ok for Approval :
Approval Rec'd :

Department Code:
Burden Flags : NNNNNNNN
WO Status : Open
Invoice State : Not Invoiced
Invoice Date :
Invoice Number :
Invoice Amount : 0.00
Order Entry No :
OE Value : 0.00
Est Margin : 0.000%
Actual Margin : 0.000%
\$0 Posted to Finished Goods

	Estimated	Actual	Var. %	Posted	To Post
Material Cost	0.00	0.00	0.00	0.00	0.00
Engineering Hours	0.00	0.00	0.00		
Engineering Cost	0.00	0.00	0.00	0.00	0.00
Production Hours	0.00	0.00	0.00		
Production Cost	0.00	0.00	0.00	0.00	0.00
Testing Hours	0.00	0.00	0.00		
Testing Cost	0.00	0.00	0.00	0.00	0.00
OverHead Hours	0.00	0.00	0.00		
OverHead Cost	0.00	0.00	0.00	0.00	0.00
SubContract Hours	0.00	0.00	0.00		
SubContract	0.00	0.00	0.00	0.00	0.00
Misc. Hours	0.00	0.00	0.00		
Misc.	0.00	0.00	0.00	0.00	0.00
Burden	0.00	0.00	0.00		
Total Cost	0.00	0.00	0.00		
Margin	0.000	0.000			
Selling Cost	0.00	0.00			

	Estimated	Actual
Labour Hrs/Amount Done	0.00	0.00
Profits/(Loss)	0.00	0.00

Bring to JB